Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-977634
Estimate date:	9 Jul 2024
Customer:	Courtney Johnson
Phone:	281-555-1314
Insurance claim:	C-1363
Vehicle:	2019 Toyota Camry
VIN:	UG8KK0P42FYMY9693
License plate:	1B550

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$381.42
Left front fender	1	$253.99
Hood panel	1	$171.86
Body labor	7.7 hrs	$522.36
Paint and materials		$290.16
TOTAL		$1,619.79

Appraiser remarks

The vehicle presents a rear quarter impact consitsent with the account given by the insured, with crumpled rear bumper cover, a cracked tail lamp housing, and scuffing that runs across the right rear panel. The damage pattern lines up well with a low-speed strike in a parking area. The repair plan calls for replacing the bumper cover, the lamp assembly, and refinishing the affected panel, with labor hours that fit the scope of this work. Parts and charges on the submitted invoices appear once each, with no duplicated entries. No prior damage to this vehicle has come to light, and the repair appears straightforward.