Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-873451
Estimate date:	2023-08-06
Customer:	Tracy Davis
Phone:	281-555-7842
Insurance claim:	C-1365
Vehicle:	2017 Toyota Camry
VIN:	BSH7CLXG8H9P08956
License plate:	7XGC 79

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$318.29
Right tail lamp assembly	1	$181.71
Rear body panel	1	$196.16
Body labor	6.1 hrs	$415.77
Paint and materials		$253.47
TOTAL		$1,365.40

Appraiser remarks

The rear bumper cover, trunk lid and both tail light assemblies show crushed plastic and cracked mounts, which is largely consistent with the reported rear-end impact. Light scuffing and a bent license plate bracket also match the direction of force described. No prior damage to this vehicle is known from our records or the owner's account. The repair labor hours listed fit the work needed to restore the affected panels and wiring. Two similar charges submitted on the same day are currently being verified against the parts and labor detail before approval. Repair plan: replace the bumper cover and tail lamps, straighten the bracket, refinish the trunk lid and blend the adjacent paint.