Mitchell Collision Center

7738 Leon Underpass Apt. 148
Baytown, TX
Phone 713-555-3433

Repair Estimate

Estimate number:	EST-960451
Estimate date:	02/07/2024
Customer:	Phillip Garza
Phone:	713-555-5041
Insurance claim:	C-1366
Vehicle:	2019 Ford F-150
VIN:	RF9VK6KN2FDC35097
License plate:	PBH 824

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$541.00
Left tail lamp assembly	1	$397.51
Rear body panel	1	$359.11
Body labor	11.7 hrs	$793.80
Paint and materials		$384.92
TOTAL		$2,476.34

Appraiser remarks

Rear bumper cover, trunk lid edge, and right taillamp assembly show crush and cracking consistent with a rear-end impact, and the repair plan addresses each panel with replacement and refinishing as needed. The labor hours listed fit the scope of this damage. No prior damage to the vehicle is known to me. I cannot say with certainty that every area noted came from this single impact, so I recommend a follow-up look at the lower quarter panel mounting points before final approval. The invoices reviewed show no repetaed charges for the same operation.