# Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-218062 |
| **Estimate date:** | 2024-12-08 |
| **Customer:** | Kevin Pearson |
| **Phone:** | 832-555-9374 |
| **Insurance claim:** | C-1367 |
| **Vehicle:** | 2023 Nissan Altima |
| **VIN:** | P8VEC15T6SPV65487 |
| **License plate:** | 665 XSC |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Headlamp assembly | 1 | $1,217.48 |
| Left front fender | 1 | $883.15 |
| Left quarter panel | 1 | $1,238.56 |
| Body labor | 106.1 hrs | $2,334.43 |
| Paint and materials | | $1,074.37 |
| TOTAL | | $6,747.99 |

### Appraiser remarks

The rear bumper cover is cracked across the left side and the left taillight assembly is broken, which fits the rear-end contact described in the claim. Damage to the trunk lid edge and the left quarter panel lines up with the reported impact direction, and no older damage to the vehicle is known. Repair time on the submitted estimate, however, runs roughly three times what this scope of work normally requires, so the labor hours should be reviewed line by line before approval. Parts pricing and invoice totals ohterwise show no repeated charges. Recommend returning the estimate to the shop for a corrected labor breakdown, then proceeding with repairs as written.