Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-449845
Estimate date:	2024-02-23
Customer:	Frank Chan
Phone:	
Insurance claim:	C-1368
Vehicle:	2018 Hyundai Elantra
VIN:	
License plate:	6K-DWIT

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$440.64
Headlamp assembly	1	$297.06
Right front door shell	1	$294.23
Body labor	15.3 hrs	$733.94
Paint and materials		$435.13
TOTAL		$2,201.00

Appraiser remarks

The front bumper cover is cracked and displaced on the driver's side, with the grille support and both headlamp brackets bent inward. The radiator support shows a clean fold consistent with a frontal strike at low speed, and the damage pattern lines up with the reported impact. No prior damage to the vehicle is known from our records or the owner's account. The repair plan calls for replacing the bumper cover and brackets, straightening the support, and refinishing the front end. Labor hours appear slightly high for this scope, so I have asked the shop to review the sequence and confirm the time allowances. The invoices reviewed show no repeated charges for the same operations.