# Patton Collision Center

518 Smith Manor Suite 165
League City, TX
Phone 281-555-6284

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-608036 |
| **Estimate date:** | 04/29/2025 |
| **Customer:** | Robert Cannon |
| **Phone:** | 281-555-7021 |
| **Insurance claim:** | C-1369 |
| **Vehicle:** | 2010 Chevrolet Malibu |
| **VIN:** | BV9V93US41PYD7549 |
| **License plate:** | 3O 7450K |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Left front fender | 1 | $1,251.03 |
| Hood panel | 1 | $1,114.51 |
| Left quarter panel | 1 | $801.81 |
| Body labor | 38.8 hrs | $2,638.52 |
| Paint and materials | | $1,559.82 |
| TOTAL | | $7,365.69 |

### Appraiser remarks

Rear bumper cover cracked across the left corner, with the left tail lamp assembly broken and the trunk lid edge scuffed. Damage pattern is largely consistent with the low-speed rear impact described by the parties. No prior damage to this vehicle is known from the file, and the repair plan calls for replacing the bumper cover and lamp, refinishing the trunk lid, and recalibrating the parking sensors. The labor hours requested fit the scope of work shown, and the invoices submitted contain no repeated line items. Recommend approval of the estimate as written, with supplements only if hidden damage is found during teardown.