Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-230241
Estimate date:	2023-11-10
Customer:	William Santos
Phone:	832-555-0107
Insurance claim:	C-1372
Vehicle:	2020 Toyota Camry
VIN:	U4KHR02D9X55U7445
License plate:	214-GJW

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,139.76
Left quarter panel	1	$1,521.50
Front bumper cover	1	$994.85
Body labor	34.6 hrs	$2,352.06
Paint and materials		$1,678.63
TOTAL		$7,686.80

Appraiser remarks

The vehicle presents with crush and scuffing along the driver side rear quarter panel, a cracked rear door glass and a bent rocker panel consistent with a side impact at an intersection. Some deformation toward the rear wheel well may predate this loss, and the file does not yet settle how much of it came from this event. The proposed repair plan covers panel replacement, refinishing, glass replacement and a frame check. The labor hours listed fit the damage described, and the parts invoices show no repeated charges. No earlier damage to this vehicle is known to us. A supplemental inspection of the wheel well area is recommended before final approval.