Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-915161
Estimate date:	May 1, 2023
Customer:	Amber Nelson
Phone:	281-555-6960
Insurance claim:	C-1374
Vehicle:	2024 Toyota Camry
VIN:	LWDG624Y24DLH5095
License plate:	402 DGN

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$970.36
Left front fender	1	$722.19
Headlamp assembly	1	$531.44
Body labor	25.1 hrs	$1,705.88
Paint and materials		$894.33
TOTAL		$4,824.20

Appraiser remarks

Rear bumper cover cracked on the driver side with the trim clip broken away, and the left tail lamp housing shattered. The pattern of scuffing and paint transfer on the bumper fits the low-speed contact described for this parking lot incident. Repair plan is to replace the bumper cover and lamp assembly, refinish the rear panel, and recalibrate the parking sensor. Labor hours line up with the work required for this damage, and the parts and invoices submitted contain no repeated line items. Nothing in the file points to earlier damage on this vehicle at this location.