Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-734938
Estimate date:	06/03/2024
Customer:	Kevin Jordan
Phone:	832-555-9107
Insurance claim:	C-1375
Vehicle:	2023 Ford F-150
VIN:	NCCS5JH88TM5K7921
License plate:	468 DCD

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$372.43
Left quarter panel	1	$233.88
Left front fender	1	$213.04
Body labor	11.7 hrs	$559.79
Paint and materials		$235.05
TOTAL		$1,614.19

Appraiser remarks

The left rear quarter panel and rear door show scraping and a crease running along the lower body line, which fits the sideswipe described during the lane change. Damage to the rear bumper cover corner is consistent with the same contact point. Nothing I found suggests earlier damage to this vehicle, and the parts and charges on the bills show no repeated entries. Labor hours look a little high for the work listed, so I recommend a line-by-line review before approval. Repair plan: replace the rear bumper cover, repair and refinish the quarter panel and door, and recheck alignment of the rear door hinge.