Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-610333
Estimate date:	7 Jun 2024
Customer:	Brandon Knight
Phone:	281-555-9424
Insurance claim:	C-1376
Vehicle:	2024 Ford F-150
VIN:	Z8NTPR1J4JKWW0287
License plate:	133 MIR

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,039.09
Headlamp assembly	1	$1,034.73
Left front fender	1	$961.92
Body labor	41.6 hrs	$2,828.98
Paint and materials		$1,483.22
TOTAL		$7,347.94

Appraiser remarks

Inspection of the veihcle confirms damage consistent with a sideswipe to the right side while changing lanes. The rear quarter panel and right rear door show scraping and deformation running along the body line, with a cracked taillight lens and scuffed bumper cover at the rear corner. The damage pattern lines up with the reported impact, and no earlier damage to the vehicle is known. The shop's repair plan calls for panel replacement, refinishing, and a light-assembly swap. The labor huors requested fit the scope of the work, and the parts and billing records show no repeated charges. I recommend approving the estimate as submitted.