Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-998228
Estimate date:	7-1-23
Customer:	Anthony Williams
Phone:	832-555-2414
Insurance claim:	C-1379
Vehicle:	2023 Kia Sorento
VIN:	8VAWHT412PBV23410
License plate:	7L 1994C

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$1,499.04
Rear body panel	1	$1,257.61
Right tail lamp assembly	1	$1,312.24
Body labor	40.7 hrs	$2,768.09
Paint and materials		$1,477.04
TOTAL		$8,314.02

Appraiser remarks

The rear bumper cover is cracked across the center with the left quarter panel crushed inward, and the trunk lid shows a folded edge. Parts and labor follow the standard body repair route: replace the bumper cover, straighten and refinish the quarter panel, and rework the trunk lid alignment. The labor hours align well with the visible damage and the work is laid out in a logical sequence. Nothing on the invoices repeats. However, some of the rear crush appears to be older than this impact, and prior-loss records describe major damage in the same areas that is now being presented as new. Before approving the full scope, the reviewer should confirm which damage belongs to this event.