Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-554697
Estimate date:	07/05/2025
Customer:	James Lopez
Phone:	346-555-6889
Insurance claim:	C-1383
Vehicle:	2019 Chevrolet Malibu
VIN:	DML8N5JH9UX9E0074
License plate:	98Y•811

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,275.85
Right tail lamp assembly	1	$1,017.64
Trunk lid	1	$841.36
Body labor	30.8 hrs	$2,092.36
Paint and materials		$1,179.01
TOTAL		$6,406.22

Appraiser remarks

The rear bumper cover is cracked across the center and the tail lamp assembly on the driver side is broken, with the trunk lid showing a crease along its lower edge. The damage pattern matches the rear impact as described, and nothing noted suggests earlier collision work on this vehicle. The planned repair covers replacing the bumper cover, the lamp assembly, and refinishing the trunk lid, with labor hours that fit the scope of the damage. The invoices reviewed contain no duplicated line items or repeated charges, so the estimate is recommended for approval as submitted.