Ross Auto Repair

8713 Caleb Brooks Apt. 930
Pasadena, TX
Phone 713-555-3105

Repair Estimate

Estimate number:	EST-141491
Estimate date:	2025-01-12
Customer:	Kathleen Gamble
Phone:	713-555-2215
Insurance claim:	C-1386
Vehicle:	2016 Honda Civic
VIN:	3U5NZ5R61ULCU8932
License plate:	

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$573.82
Left tail lamp assembly	1	$571.28
Right tail lamp assembly	1	$324.32
Body labor	19.3 hrs	$1,314.32
Paint and materials		$718.31
TOTAL		$3,502.05

Appraiser remarks

The rear bumper cover, trunk lid and both tail lamp assemblies show the damage expected from a rear-end impact, and the crush pattern on the rear panel matches the reported direciton of force. No prior damage to this vehicle is known from our records or the inspection. The labor hours listed fit the scope of work required to replace and refinish the affected parts. Two similar charges posted on the same day are being verified against the invoices before approval. Repair plan: replace the bumper cover, trunk lid and lamps, repair the rear panel, then refinish and recalibrate the rear sensors.