Allen Auto Repair

71822 Arroyo Expressway
Katy, TX
Phone 346-555-3834

Repair Estimate

Estimate number:	EST-297509
Estimate date:	5-28-23
Customer:	Kathryn Melton
Phone:	713-555-3721
Insurance claim:	C-1387
Vehicle:	2021 Ford F-150
VIN:	AZM5G6FS8U7FD3255
License plate:	

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,363.12
Headlamp assembly	1	$1,090.25
Left quarter panel	1	$873.39
Body labor	30.3 hrs	$2,062.63
Paint and materials		$1,162.11
TOTAL		$6,551.50

Appraiser remarks

The vehicle shows front-quarter and bumper damage on the driver's side, with the bumper cover cracked and the fender pushed inward near the headlamp. The pattern lines up with a frontal strike at an angle, which is consistent with a vehicle turning across oncoming traffic and being hit on its frnot corner. Repair plan calls for replacing the bumper cover and fender, refinishing adjacent panels, and realigning the headlamp bracket. The labor huors listed fit the damage shown, and the parts and charges are billed once with no repeated line items. There is no sign of earlier damage to this vehicle in the records reviewed.