Ross Auto Repair

8713 Caleb Brooks Apt. 930
Pasadena, TX
Phone 713-555-3105

Repair Estimate

Estimate number:	EST-914786
Estimate date:	2025-01-10
Customer:	Jeff Hoffman
Phone:	346-555-4938
Insurance claim:	C-1388
Vehicle:	2013 Toyota Camry
VIN:	5C6U2A2Z2Z88H2896
License plate:	5Y 86283

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,188.13
Headlamp assembly	1	$895.94
Left quarter panel	1	$872.13
Body labor	31.5 hrs	$2,140.18
Paint and materials		$867.39
TOTAL		$5,963.77

Appraiser remarks

Vehicle inspected at the shop following a side impact at an intersection. The primary damage is on the driver's side: the front door panel is deformed, the rear quarter panel is creased, and the side sill shows scuffing consistent with the reported collision direction. Repair plan calls for panel replacement on the door, straightening and refinishing of the quarter panel, and a recalibration of the side curtain airbag sensor. The labor hours requested match the extent of the deformation seen. Invoices reviewed contain no repeated line items. No prior damage to this vehicle is known from the file.