Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-558210
Estimate date:	2024-09-10
Customer:	Craig Hoffman
Phone:	346-555-5244
Insurance claim:	C-1389
Vehicle:	2018 Jeep Cherokee
VIN:	4Z55XNRT8RPH41446
License plate:	TZW 571

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$422.78
Left tail lamp assembly	1	$463.45
Right tail lamp assembly	1	$300.20
Body labor	12.5 hrs	$852.87
Paint and materials		$515.73
TOTAL		$2,555.03

Appraiser remarks

Rear bumper cover cracked across the center with the lower valance torn away, and the left tail lamp assembly broken. The trunk lid shows a crease at the lower edge and the rear panel has a buckled area consistent with a straight-on rear impact, which matches the impact as described. Repair plan calls for replacing the bumper cover and tail lamp, repairing the trunk lid, refinishing the rear panel, and checking the parking sensor wiring. The labor hours submitted fit the extent of the damage. The invoices show no repeated charges. No earlier damage to this vehicle is known to us, and the photos show no older rust or filler in the affected areas.