Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-884021
Estimate date:	09/14/2024
Customer:	Jennifer Zuniga
Phone:	281-555-3244
Insurance claim:	C-1391
Vehicle:	2023 Chevrolet Malibu
VIN:	0FP3SF9Z8GZJ37755
License plate:	

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$994.07
Front bumper cover	1	$827.74
Left quarter panel	1	$1,041.02
Body labor	38.7 hrs	$2,633.48
Paint and materials		$1,412.22
TOTAL		$6,908.53

Appraiser remarks

The front bumper cover is cracked across the center and the radiator support shows crush consistent with a forntal strike at low speed. Both headlamp assemblies are broken, the hood latch has deformed, and the grille has pulled loose from its mounts. The damage pattern matches the impact as described. Repair will involve replacing the bumper cover, both lamps, and the hood latch, with straightening and refinishing of the support. The labor hours on this plan fit the scope of damage. No earlier damage to this vehicle is known. Two similar billing entries posted on the same day are currently under review and have not yet been approved.