Ross Auto Repair

8713 Caleb Brooks Apt. 930
Pasadena, TX
Phone 713-555-3105

Repair Estimate

Estimate number:	EST-920243
Estimate date:	2024-08-18
Customer:	Patrick Gray
Phone:	281-555-6418
Insurance claim:	C-1394
Vehicle:	2018 Nissan Altima
VIN:	W3WC2SUZ3B4907861
License plate:	

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,357.56
Hood panel	1	$1,874.18
Headlamp assembly	1	$1,114.99
Body labor	46.8 hrs	$3,180.67
Paint and materials		$1,337.33
TOTAL		$8,864.73

Appraiser remarks

Vehicle was struck on the front driver's side corner while the other car was turning left across its path. The damage visible on the front bumper cover, driver-side headlamp assembly, fenedr and hood leading edge lines up well with that kind of impact, and the pattern is consistent from one panel to the next. Repair will involve replacing the bumper cover and headlamp, straightening and refinishing the fender, and blending the hood. The labor hours requested fit what I see on the car. Nothing in the file or the vehicle suggests earlier damage to this area, and the billing history shows no repeated charges for the same work.