Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-857698
Estimate date:	5-7-24
Customer:	Devon Rogers
Phone:	281-555-8183
Insurance claim:	C-1395
Vehicle:	2010 Ford F-150
VIN:	ZF0MZWJ071HLM7963
License plate:	478-641

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,244.87
Headlamp assembly	1	$1,303.12
Hood panel	1	$1,114.38
Body labor	39.2 hrs	$2,662.54
Paint and materials		$995.34
TOTAL		$7,320.25

Appraiser remarks

The rear bumper cover is cracked across the center with the left taillight assembly pushed inward, and the trunk lid shows a creased edge on the driver's side. The paint transfer and crush pattern line up with the reported low-speed impact in the lot, so the damage is consistent with the account given. The repair plan calls for replacing the bumper cover and taillight, refinishing the trunk lid, and a scan for sensor function. The labor hours requested fit the scope of this work. Nothing in the file points to earlier damage on this vehicle, and the invoices submitted list each item once with no repeated charges.