Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-524533
Estimate date:	10/04/2023
Customer:	Edward Luna
Phone:	281-555-8777
Insurance claim:	C-1396
Vehicle:	2022 Hyundai Elantra
VIN:	0ZCR0PXW5UPTS4161
License plate:	

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,119.91
Left front fender	1	$767.21
Headlamp assembly	1	$945.90
Body labor	35.8 hrs	$2,432.76
Paint and materials		$1,449.59
TOTAL		$6,715.37

Appraiser remarks

Vehicle was struck on the driver side rear quarter panel at the intersection. Damage is consistent with the reported side impact: the rear door shell is creased, the quarter panel has a deep dent running toward the wheel arch, and the rear bumper bracket is bent. No earlier damage is known on this vehicle, and the body shop invoices show no repeated charges for the same work. Proposed repair includes replacing the rear door, straightening and refinishing the quarter panel, and replacing the bracket. The labor hours listed are in line with the extent of this damage and are reasonable for the repair plan.