Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-846965
Estimate date:	April 19, 2024
Customer:	Stephanie Browning
Phone:	832-555-2229
Insurance claim:	C-1397
Vehicle:	2014 Kia Sorento
VIN:	PK4S7ZKRX1PVS4876
License plate:	

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,280.46
Headlamp assembly	1	$1,230.72
Left quarter panel	1	$1,168.27
Body labor	47.2 hrs	$3,209.38
Paint and materials		$1,628.11
TOTAL		$8,516.94

Appraiser remarks

Rear bumper cover cracked across the left corner, with the tail lamp assembly broken and the trunk lid edge scuffed in a way that matches a low-speed strike from behind. The damaegd panels line up with the impact described, and nothing on the vehicle points to older unrepaired harm. The proposed plan replaces the bumper cover and lamp, repairs and refinishes the lid edge, and recalibrates the parking sensors. The labor hours requested fit the scpoe of the work, and the invoices show each operation billed once with no duplicated charges. Recommend approval as submitted.