Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-718319
Estimate date:	2023-01-03
Customer:	Ryan Nelson
Phone:	832-555-9330
Insurance claim:	C-1398
Vehicle:	2016 Kia Sorento
VIN:	89CGGMVB7WUHB4491
License plate:	JZ-8109

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$939.68
Headlamp assembly	1	$867.30
Left quarter panel	1	$936.72
Body labor	37.2 hrs	$1,787.55
Paint and materials		$809.41
TOTAL		$5,340.66

Appraiser remarks

The vehicle shows a side impact to the driver-side rear quarter panel, with a crushed rear door, a cracked taillight lens, and scuffing along the rocker panel. Most of the damage lines up with the impact described at the intersection. Parts pricing and the paint blend on the adjacent panel look reasonable. The estimated labor hours run slightly high for a repair of this extent, so the shop should be asked to justify the time on the door reskin and the quarter panel alignment. The invoices show no duplicated charges. No prior damage to this vehicle is known. Recommended plan: replace the rear door, repair and refinish the quarter panel, install a new taillight assembly, and recheck the frame measurements bfeore final payment.