Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-286107
Estimate date:	02/13/2024
Customer:	Alan Beard
Phone:	
Insurance claim:	C-1399
Vehicle:	2015 Ford F-150
VIN:	KFZW5D0W8GHM29354
License plate:	OZG-0199

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,544.40
Headlamp assembly	1	$1,448.42
Right front door shell	1	$1,068.15
Body labor	40.2 hrs	$2,731.56
Paint and materials		$1,550.33
TOTAL		$8,342.86

Appraiser remarks

Inspection of the front end shows the bumper cover cracked across the center, the grille mount broken, and the hood leading edge bent upward, with the radiator support and both headlamp brackets displaced. The damage pattern is consistent with the reported head-on impact at low speed, and no prior damage to the vehicle is known from the records reviewed. The reapir plan calls for replacing the bumper cover, grille, and hood, along with straightening the radiator support and refinishing the affected panels. The labor hours submitted fit the damage described. Two similar charges posted on the same day are currently being checked against the shop invoices before final approval.