Smith Collision Center

4687 James Forge Apt. 980
Baytown, TX
Phone 713-555-0978

Repair Estimate

Estimate number:	EST-249680
Estimate date:	3-29-25
Customer:	Steven Stanley
Phone:	281-555-3324
Insurance claim:	C-1400
Vehicle:	2018 Toyota Camry
VIN:	H9JM75UE5KFRY9211
License plate:	3QO 346

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$273.70
Left tail lamp assembly	1	$253.17
Rear bumper cover	1	$182.92
Body labor	7.5 hrs	$509.92
Paint and materials		$241.66
TOTAL		$1,461.37

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp assembly broken and the trunk lid edge creased. Damage pattern is consistent with the reported rear impact, and no prior damage to the vehicle is known to us. Repair plan calls for replacing the bumper cover and tail lamp, straightening the trunk lid, and refinishing the affected panels. Labor hours submitted fit the scope of this damage. Two similar charges posted on the same day are currently under review before the estimate is finalized.