Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-887854
Estimate date:	11/28/2023
Customer:	Samantha Fowler
Phone:	281-555-6940
Insurance claim:	C-1402
Vehicle:	2012 Honda Civic
VIN:	YVK82LST1HUD33262
License plate:	57-86535

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,116.32
Rear bumper reinforcement	1	$920.00
Right tail lamp assembly	1	$654.23
Left tail lamp assembly	1	$1,116.32
Body labor	29.2 hrs	$1,983.89
Paint and materials		$1,038.43
TOTAL		$6,829.19

Appraiser remarks

The rear bumper cover is cracked and displaced, with the tail lamp assembly broken on the driver's side and the trunk lid edge bent inward. Crush depth and the pattern of damage on the quarter panel are mostly in line with the impact descirbed by the parties. Repair labor hours fit the extent of the damage, and no earlier damage to this vehicle is known from our records or the prior file. The estimate includes one charge for a service that appears twice on the same invoice; the shop has acknowledged the second entry was a repeat and it should be removed. Recommended plan: replace the bumper cover, tail lamp, and trunk lid edge, then refinish and blend the adjacent panels.