King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

Repair Estimate

Estimate number:	EST-242695
Estimate date:	May 22, 2023
Customer:	Joshua Lee
Phone:	281-555-1260
Insurance claim:	C-1404
Vehicle:	2014 Jeep Cherokee
VIN:	2384RAJU50NS05212
License plate:	HON 292

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,348.06
Hood panel	1	$953.51
Headlamp assembly	1	$592.05
Body labor	29.3 hrs	$1,995.62
Paint and materials		$1,427.44
TOTAL		$6,316.68

Appraiser remarks

The vehicle shows scraping and a dented, creased rear quarter panel on the passenger side, with a cracked taillight lens and paint transfer along the lower door. The pattern of damage lines up with the sideswipe described during the lane change, and nothing on the car points to a different cause. The repair plan calls for replacing the rear quarter panel, refinishing the adjoining door, and swapping the taillight assembly, with labor hours that fit the work involved. The shop's invoices list each item once with no repeated charges. We have no record or sign of earlier damage to this vehicle in the same area, so the repair scope can be approved as written.