Mendoza Collision Center

47116 Jones Roads
Houston, TX
Phone 281-555-2941

Repair Estimate

Estimate number:	EST-264340
Estimate date:	August 2, 2024
Customer:	Aaron Gonzalez
Phone:	713-555-0272
Insurance claim:	C-1406
Vehicle:	2014 Nissan Altima
VIN:	6DX4PLJJ3LNCB0547
License plate:	070 GNT

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$292.19
Right tail lamp assembly	1	$301.77
Trunk lid	1	$239.15
Body labor	9.0 hrs	$610.44
Paint and materials		$438.98
TOTAL		$1,882.53

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp housing broken, and the trunk lid edge shows creasing consistent with the reported rear-end impact. The damage pattern lines up with the described collision and the repair plan calls for replacing the bumper cover, tail lamp assembly and trunk lid seal, followed by refinishing the rear panel. Labor hours are in line with the work required to address this damage. The billing reviewed shows no repeated charges for the same operation. A few faint scratches on the lower quarter panel appear older than this crash and are noted here for reference, though they are not part of the repair scope.