Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-357032
Estimate date:	July 4, 2023
Customer:	Maria Jimenez
Phone:	281-555-2010
Insurance claim:	C-1407
Vehicle:	2016 Nissan Altima
VIN:	YJ2L3L7M1T4FM9490
License plate:	Z06 1FO

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$917.58
Trunk lid	1	$635.68
Rear body panel	1	$673.85
Body labor	19.8 hrs	$1,344.54
Paint and materials		$804.20
TOTAL		$4,375.85

Appraiser remarks

Rear bumper cover cracked and displaced, tail lamp assembly broken on the driver side, and trunk lid edge deformed with the panel seam showing stress. Damage pattern is largely consistent with the impact described by the insured. Repair plan calls for replacing the bumper cover and lamp assembly, straightening the trunk lid flange, and refinishing the affected panels. Labor hours submitted fit the scope of the damage. Shop invoices show no repeated charges for the same operations. No prior damage to this vehicle is on record. Recommend approval of the repair as written.