Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-255430
Estimate date:	5-29-24
Customer:	Linda Taylor
Phone:	832-555-6547
Insurance claim:	C-1408
Vehicle:	2018 Hyundai Elantra
VIN:	5TKDF9FR3WG7T7009
License plate:	75E-YRVW

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,543.77
Right front door shell	1	$1,214.24
Headlamp assembly	1	$790.20
Body labor	30.0 hrs	$2,036.78
Paint and materials		$1,313.88
TOTAL		$6,898.87

Appraiser remarks

Vehicle presented for estimate following a collision during a left-hand turn. Damage observed is concentrated on the front driver-side corner, including a cracked bumper cover, a bent headlamp bracket, a damaged fender, and a broken grille clip. The pattern of crush and displacement is consistent with the impact described by the insured. A few light scratches elsewhere on the body appear weathered and may predate this loss; they are noted but are not included in the repair scope. Proposed plan is to replace the bumper cover and fender, repair the bracket and hood alignment, and refinish the affected panels. Labor hours listed on the estimate are in line with the damage found. The supporting invoices reviewed show no repeated charges for the same work.