Williams Auto Body

998 Donovan Ford Suite 346
Pearland, TX
Phone 832-555-7510

Repair Estimate

Estimate number:	EST-230966
Estimate date:	03/11/2024
Customer:	Michelle Nicholson
Phone:	346-555-3678
Insurance claim:	C-1409
Vehicle:	2011 Kia Sorento
VIN:	43567BF27450A7388
License plate:	IUG6521

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$341.40
Left front fender	1	$252.77
Right front door shell	1	$230.21
Body labor	26.3 hrs	$579.68
Paint and materials		$340.56
TOTAL		$1,744.62

Appraiser remarks

The right rear quarter panel and rear bumper cover show scuffing, a cracked lower reflector, and a dented rear door skin consistent with a sideswipe along the passenger side during a lane change. The pattern of contact lines up with the reported impact, and no prior damage to these panels is known. The labor hours on this estimate run roughly three times what a repair of this scope would normally require, so the figure is under review. Two similar charges posted on the same day are also being checked beofre approval. Recommended plan: replace the reflector and bumper cover, repair the door skin, and refinish the affected panels, with the labor revised to match the actual scope.