Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-924559
Estimate date:	16 Apr 2023
Customer:	Johnny Kim
Phone:	281-555-9833
Insurance claim:	C-1411
Vehicle:	2015 Honda Civic
VIN:	LW21WR8U4LFGW9008
License plate:	481 BXO

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,509.86
Headlamp assembly	1	$1,398.22
Hood panel	1	$685.98
Body labor	32.8 hrs	$2,228.12
Paint and materials		$1,537.70
TOTAL		$7,359.88

Appraiser remarks

The vehicle shows damage consistent with the impact described, mainly to the front bumper cover, left headlamp assembly and left fender, with the damage pattern lining up with a side-on collision during a left turn. Nothing in the file points to earlier damage to this vehicle. The repair plan calls for replacing the bumper cover and headlamp, refinishing and blenidng the fender, and recalibrating the driver assistance sensor mounted behind the bumper. The labor hours requested fit the scope of this damage. The billing records reviewed show no repeated charges for the same work.