Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-694796
Estimate date:	10/12/2024
Customer:	David Anderson
Phone:	832-555-4742
Insurance claim:	C-1413
Vehicle:	2016 Toyota Camry
VIN:	XGZEZ0U0707L00120
License plate:	KBP 679

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$1,508.40
Left tail lamp assembly	1	$1,124.53
Rear bumper cover	1	$921.13
Body labor	36.9 hrs	$2,508.63
Paint and materials		$1,490.10
TOTAL		$7,552.79

Appraiser remarks

The rear bumper cover is cracked and displaced on the driver's side, with the trunk lid edge deformed and the left tail lamp housing broken. The reinforcement bar appears bent but is not yet fully exposed for inspection. Some of the scuffing on the lower quarter panel may predate this impact, though it is hard to tell from the photos alone. No earlier damage to the vehicle is known to us. The repair plan calls for replacing the bumper cover and tail lamp, straightening the trunk lid, and refinishing the affected panels. The bills submitted show no repeated charges, and the labor hours requested fit the damage described.