White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-849486
Estimate date:	November 15, 2023
Customer:	Andrea Ashley
Phone:	713-555-9149
Insurance claim:	C-1414
Vehicle:	2014 Hyundai Elantra
VIN:	M4VNGC8X34CHH8264
License plate:	

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,006.94
Rear bumper reinforcement	1	$1,411.10
Trunk lid	1	$1,188.92
Body labor	120.6 hrs	$2,653.61
Paint and materials		$1,297.04
TOTAL		$7,557.61

Appraiser remarks

The rear bumper cover is cracked across the center with the left tail lamp assembly broken, and the trunk lid shows a crease consistent with the reported rear impact. The damage pattern liens up with the described collision, and nothing I found points to earlier damage on this vehicle. The plan calls for replacing the bumper cover and tail lamp, refinishing the trunk lid, and checking the rear panel for hidden deformation. The labor hours requested run roughly three times what a job of this scope normally needs, so I have asked the shop to justify each operation line by line before approval. The invoices and parts records I reviewed show no repeated charges.