Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-596129
Estimate date:	28 Apr 2025
Customer:	David Smith
Phone:	832-555-2673
Insurance claim:	C-1415
Vehicle:	2015 Jeep Cherokee
VIN:	CUKPTY5A0VUK51249
License plate:	213 PX1

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$379.89
Left quarter panel	1	$358.76
Hood panel	1	$199.10
Body labor	13.8 hrs	$660.32
Paint and materials		$311.89
TOTAL		$1,909.96

Appraiser remarks

The front bumper cover is cracked across the center, the grille support has bent, and the hood latch and both headlamp assemblies show impact marks consistent with a frontal strike at low speed. Damage pattern lines up well with the account of the collision, and nothing in the file points to prior damage on this vehicle. The repair plan calls for replacing the bumper cover and headlamps, straightening the radiator support, and refinishing the hood and bumper area. Labor hours on the shop's estimate run slightly above what I would expect for this scope, so I have asked the shop to review the time allowances. The invoices submitted show no repeated charges.