Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-112495
Estimate date:	6-12-24
Customer:	Jessica Gordon
Phone:	713-555-6007
Insurance claim:	C-1416
Vehicle:	2017 Honda Civic
VIN:	XY8Y6RJH5RDBH4283
License plate:	955 AJF

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$849.36
Right tail lamp assembly	1	$1,110.31
Trunk lid	1	$563.37
Body labor	23.9 hrs	$1,627.34
Paint and materials		$1,027.56
TOTAL		$5,177.94

Appraiser remarks

The rear bumper cover is cracked across the center and the left tail lamp assembly is broken, with the trunk lid showing deformation along its lower edge. The damage pattern is consistent with the reported impact direction and height. The plan calls for replacing the bumper cover, tail lamp, and trunk panel, with refinishing and a pre-scan of the rear sensors. Labor hours fit the extent of the damage shown. A few light scratches on the right quarter panel appear older than this loss and have been noted separately. Two smiilar charges posted to the file on the same day are under review before payment is released.