Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-665441
Estimate date:	June 29, 2024
Customer:	Corey Petty
Phone:	832-555-2340
Insurance claim:	C-1417
Vehicle:	2021 Chevrolet Malibu
VIN:	K3MJRJZL9NAK49017
License plate:	55CO049

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,217.04
Left quarter panel	1	$1,023.20
Left front fender	1	$1,091.05
Body labor	39.5 hrs	$2,687.83
Paint and materials		$1,677.57
TOTAL		$7,696.69

Appraiser remarks

Vehicle inspected at the shop following a left-turn collision. The damage to the front driver-side quarter panel, bumper bracket, and headlamp assembly is largely consistent with the impact described by the owner. Repair plan calls for replacing the bumper cover and headlamp, repairing the fender, and refinishing adjacent panels. Labor hours requested match the scope of the damage shown. Itemized invoices reviewed; no duplicate charges appear. No prior damage to this vehicle is known from our records or the owner's account.