Shea Collision Center

75655 Mia Isle Suite 746
Houston, TX
Phone 346-555-1545

Repair Estimate

Estimate number:	EST-270058
Estimate date:	July 5, 2024
Customer:	Linda Arnold
Phone:	713-555-2172
Insurance claim:	C-1418
Vehicle:	2015 Nissan Altima
VIN:	ARCYHLN66FPPZ0923
License plate:	83E•463

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$304.27
Rear body panel	1	$316.98
Left tail lamp assembly	1	$175.11
Body labor	14.0 hrs	$671.18
Paint and materials		$278.17
TOTAL		$1,745.71

Appraiser remarks

The rear bumper cover is cracked across its lower section, and the tail lamp assembly on the driver's side is broken. The trunk lid shows a crease running toward the center, with paint transfer consistent with the reported impact. A few older scratches are visible on the lower quarter panel and may predate this loss. Most of the listed damage fits the described collision. The repair plan calls for replacing the bumper cover and lamp, straightening the trunk lid, and refinishing the affected panels. The labor hours requested run slightly above what this damage tyipcally requires, so a review of the allocated time is recommended before approval.