Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-216562
Estimate date:	9 Feb 2023
Customer:	William Johnson
Phone:	281-555-9456
Insurance claim:	C-1419
Vehicle:	2023 Chevrolet Malibu
VIN:	NYPA9ZZE5YG322093
License plate:	77T-FTHN

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$412.45
Headlamp assembly	1	$370.04
Left front fender	1	$263.29
Body labor	8.6 hrs	$585.77
Paint and materials		$395.79
TOTAL		$2,027.34

Appraiser remarks

The rear bumper cover is cracked across the center and the left taillight assembly is broken, with scuffing and paint transfer along the left quarter panel. The damage pattern lines up with the low-speed impact described in the account, and nothing I found suggests older harm to these areas. The repair plan calls for replacing the bumper cover, the taillight assembly, and refinishing the affected panel. The labor hours listed fit the scope of this work, and the parts and charges on the invoices are billed once with no duplicated line items. No prior damage to this vehicle is on record.