Gonzalez Auto Body

27193 Lyons Trafficway
Baytown, TX
Phone 281-555-9912

Repair Estimate

Estimate number:	EST-739645
Estimate date:	1-23-25
Customer:	Pamela Church
Phone:	713-555-2529
Insurance claim:	C-1420
Vehicle:	2023 Jeep Cherokee
VIN:	LU7AM6620DCL12984
License plate:	327-532

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,081.29
Hood panel	1	$1,106.63
Front bumper cover	1	$946.78
Body labor	45.2 hrs	$2,168.60
Paint and materials		$1,443.05
TOTAL		$6,746.35

Appraiser remarks

The vehicle presents front-quarter damage on the driver side, consistent with the reported collision during a left turn. The bumper cover is cracked across its left end, the fender shows buckling along the upper edge, and the headlamp assembly has a broken mounting tab. The damage pattern lines up with the impact as described. No prior damage to the vehicle is known to us. The repair plan calls for replacing the bumper cover and headlamp, straightening and refinishing the fender, and aligning the front suspension. Labor hours for the plan run slightly high for this scope of damage, and we recommend a line-by-line review before approval. The invoices submitted show no repeated charges.