Guerrero Auto Body

83242 Brian Turnpike Suite 994
League City, TX
Phone 713-555-7464

Repair Estimate

Estimate number:	EST-668312
Estimate date:	2024-06-14
Customer:	Johnathan Mosley
Phone:	713-555-5149
Insurance claim:	C-1421
Vehicle:	2020 Ford F-150
VIN:	DA59737P7YZKX1060
License plate:	4209

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$890.89
Front bumper cover	1	$923.56
Left quarter panel	1	$539.33
Body labor	28.5 hrs	$1,936.62
Paint and materials		$983.32
TOTAL		$5,273.72

Appraiser remarks

The rear bumper cover is cracked across the center and the left taillight assembly is broken, with scuffing running down the left quarter panel. The pattern of damage lines up with the low-speed contact described for this parking lot incident, and nothing I found suggests older impact marks or prior repair work on this vehicle. The labor hours requested fit the replacement and refinishing needed, and the parts list contains no duplicated line items. Recommended plan: replace the bumper cover and taillight assembly, blend and refinish the quarter panel, and recheck the parking sensor wiring once the panels are off.