Allen Auto Repair

71822 Arroyo Expressway
Katy, TX
Phone 346-555-3834

Repair Estimate

Estimate number:	EST-239703
Estimate date:	5-15-23
Customer:	Dawn Simmons
Phone:	832-555-9021
Insurance claim:	C-1422
Vehicle:	2022 Hyundai Elantra
VIN:	87VUU80H3WRUK7685
License plate:	SFN 590

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,583.42
Headlamp assembly	1	$968.92
Left front fender	1	$1,152.99
Body labor	39.2 hrs	$2,664.97
Paint and materials		$1,732.60
TOTAL		$8,102.90

Appraiser remarks

Vehicle shows damage to the front bumper cover, left headlamp assembly, and hood leading edge, with crushed radiator support brackets and a cracked grille. The pattern of contact is consistnet with a left-turn collision where the front corner struck another vehicle's side. Repair plan calls for replacing the bumper cover, headlamp, and hood, along with straightening the support brakcets and refinishing the affected panels. Labor hours fit the scope of this damage. Billing from the shop shows no repeated charges for the same operations. Nothing in the file points to earlier damage on this vehicle at these locations.