Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-514481
Estimate date:	September 9, 2024
Customer:	Kelly Romero
Phone:	346-555-9630
Insurance claim:	C-1423
Vehicle:	2016 Hyundai Elantra
VIN:	PM1UAY882PJH40631
License plate:	462-OXM

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$391.57
Right front door shell	1	$243.46
Hood panel	1	$212.25
Body labor	8.5 hrs	$580.68
Paint and materials		$276.71
TOTAL		$1,704.67

Appraiser remarks

The rear quarter panel and left taillight assembly show deformation consistent with a collision while turning left, with the impact pattern lining up with the account given. The damage is limited to the expected area, and no older damage was found or reported on this vehicle. The repair plan calls for panel replacement, refinishing, and light assembly installation. The labor hours quoted fit the scope of the work, and the parts and invoices submitted contain no repeated charges. Recommend approval of the estimate as written.