Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-730019
Estimate date:	24 Jul 2024
Customer:	Hannah Smith
Phone:	346-555-1875
Insurance claim:	C-1426
Vehicle:	2024 Toyota Camry
VIN:	
License plate:	

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$373.64
Front bumper cover	1	$282.66
Left front fender	1	$310.62
Body labor	10.1 hrs	$684.95
Paint and materials		$384.34
TOTAL		$2,036.21

Appraiser remarks

The vehicle presents with a crushed rear quarter panel, a cracked taillight assembly and scuffing across the bumper cover, consistent with the low-speed parking lot impact described by the insured. Most of the damage lines up with that account, and no earlier damage to the vehicle is known from the file. The repair plan calls for replaicng the bumper cover, refinishing the quarter panel and reinstalling the lamp assembly. The labor hours requested fit the scope of work, and the invoices submitted show no repeated charges. Recommend approval of the estimate as submitted.