Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-312428
Estimate date:	July 10, 2024
Customer:	Allen Mills
Phone:	281-555-6621
Insurance claim:	C-1427
Vehicle:	2013 Kia Sorento
VIN:	FV2BXMEV5JAK69821
License plate:	D63-PHA

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,424.14
Left front fender	1	$1,679.61
Right front door shell	1	$999.94
Body labor	39.0 hrs	$2,655.32
Paint and materials		$1,301.06
TOTAL		$8,060.07

Appraiser remarks

Vehicle was struck on the rear quarter panel while turning left, and the damage seen on the car lines up well with that description. The rear bumper cover is cracked at the left corner, the left quarter panel shows a crease with paint loss, and the tail light assembly is broken. Nothing about the pattern suggests an earlier loss, and no prior damage to this vehicle is known. The plan is to replace the bumper cover, repair and refinish the quarter panel, and install a new lamp assembly. The labor hours on the estimate are in line with this scope of work, and the repair invoices on file show no repeated charges for the same items.