Williams Auto Body

998 Donovan Ford Suite 346
Pearland, TX
Phone 832-555-7510

Repair Estimate

Estimate number:	EST-269183
Estimate date:	10/10/2023
Customer:	Gregory Hopkins
Phone:	346-555-7700
Insurance claim:	C-1428
Vehicle:	2011 Jeep Cherokee
VIN:	YEDUBT5J7PVNE4645
License plate:	6BEN897

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$1,106.44
Rear body panel	1	$882.89
Rear bumper reinforcement	1	$631.12
Body labor	22.5 hrs	$1,531.82
Paint and materials		$1,127.01
TOTAL		$5,279.28

Appraiser remarks

The rear bumper cover is cracked across its center and the left tail lamp assembly is shattered, with scuffing and a crushed reinforcement bar that line up with a straight rear-end impact. Damage to the trunk floor support and the adjacent quarter panel matches the same direction of force, and nothing observed points to older repairs or prior collision work on this vehicle. The plan is to replace the bumper cover, tail lamp, and reinforcement bar, then refinish the rear panel and recalibrate the parking sensors. The laobr hours listed fit the scope of this damage, and the invoices submitted show no repeated charges for the same operations.