Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-713652
Estimate date:	30 May 2025
Customer:	Ryan Little
Phone:	832-555-7303
Insurance claim:	C-1429
Vehicle:	2021 Ford F-150
VIN:	JP781UV245TEK2491
License plate:	87U•762

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,497.94
Hood panel	1	$1,534.64
Headlamp assembly	1	$1,215.81
Body labor	35.6 hrs	$2,417.92
Paint and materials		$1,095.04
TOTAL		$7,761.35

Appraiser remarks

The front bumper cover is cracked across the center and the grille support has bent inward, with the radiator core support showing a clean fracture near the left mount. Both headlamp assemblies are broken, and the hood latch and left fender edge show crush consistent with a frontal strike at low speed. The repair plan calls for replacing the bumper cover, grille, headlamp units, and hood latch, straightening the core support, and refinishing the affected panels. The labor hours requested match the scope of this damage. The shop's invoices list each part and operation once, with no duplicate charges. Nothing in the vehicle history or owner statement suggests earlier damage to these areas.