King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

Repair Estimate

Estimate number:	EST-282431
Estimate date:	May 2, 2023
Customer:	Connie Davis
Phone:	281-555-2541
Insurance claim:	C-1430
Vehicle:	2020 Hyundai Elantra
VIN:	R5CTZBEF4U1JR2904
License plate:	0OJ72

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,107.42
Left front fender	1	$930.43
Headlamp assembly	1	$893.76
Body labor	31.0 hrs	$2,109.45
Paint and materials		$1,076.95
TOTAL		$6,118.01

Appraiser remarks

Vehicle inspected at the body shop following a low-speed collision in a parking lot. The damage to the rear bumper cover, left quarter panel and tail lamp assembly is largely consistent with the impact described by the insured. Repair plan calls for replacing the bumper cover, refinishing the quarter panel, and installing a new tail lamp, with labor hours that fit the extent of the damage. Invoice lines reviewed show no duplicated charges. No prior damage to the vehicle has been identified in the records or during inspection. Parts pricing and paint materials are standard for this model year.