Oconnell Auto Body

9663 Brittany Village
Sugar Land, TX
Phone 713-555-4919

Repair Estimate

Estimate number:	EST-867223
Estimate date:	2025-06-03
Customer:	Michael Townsend
Phone:	346-555-5618
Insurance claim:	C-1431
Vehicle:	2011 Ford F-150
VIN:	UYT6VZH19892T5485
License plate:	873 7XM

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$625.45
Hood panel	1	$660.97
Left quarter panel	1	$418.51
Body labor	14.5 hrs	$984.73
Paint and materials		$709.91
TOTAL		$3,399.57

Appraiser remarks

The vehicle shows scraping and a crease along the right rear quarter panel, with the rear bumper cover cracked at its right end and the right taillamp housing chipped. The pattern of contact runs in a consistent line from the rear wheel arch toward the bumper corner, which fits the sideswipe described during the lane change. The repair plan calls for replacing the bupmer cover, refinishing the quarter panel, and replacing the taillamp housing, with labor hours that are in line with the work shown. Nothing on the vehicle points to older damage in this area, and the invoices submitted list each task once with no repeated charges.