Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-100412
Estimate date:	12/01/2023
Customer:	Roger Hoffman
Phone:	346-555-9177
Insurance claim:	C-1432
Vehicle:	2010 Ford F-150
VIN:	UTVVD26G8YHFJ2352
License plate:	

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$547.10
Headlamp assembly	1	$536.62
Right front door shell	1	$368.21
Body labor	13.6 hrs	$926.64
Paint and materials		$571.56
TOTAL		$2,950.13

Appraiser remarks

The front bumper coevr is cracked and displaced on the driver side, with the upper radiator support bracket bent and the hood latch assembly deformed. The headlamp housing is cracked at its mounting points, and the grille retainers are broken. The pattern of crush and paint transfer lines up with the reported frontal contact at low speed, and nothing I observed points to earlier damage on this vehicle. The repair plan replaces the bumper cover, bracket, latch and headlamp, then refinishes and recalibrates the sensor mounts. The labor hours on the estimate are consistent with the work described, and the parts and charges on the invoices show no repeated entries.