Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-236450
Estimate date:	09/17/2024
Customer:	Patricia Reed
Phone:	713-555-2276
Insurance claim:	C-1433
Vehicle:	2021 Toyota Camry
VIN:	MRK32TVKXYL9J1586
License plate:	415 URP

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$674.36
Headlamp assembly	1	$428.81
Hood panel	1	$418.64
Body labor	24.6 hrs	$1,179.70
Paint and materials		$524.53
TOTAL		$3,226.04

Appraiser remarks

The front bumper cover is cracked across the center and the radiator support is bent, which fits the low-speed frontal impact described. The hood latch and both headlamp assemblies show crush marks consistent with the same event. Most of the damage lines up well with the reported collision. Two similar charges posted on the same day are still being reviewed against the parts invoices. The labor hours look a little high for this scope of work and should be checked against the standard repair times. No prior damage to the vehicle is known. Recommended plan: replace the bumper cover, radiator support, hood latch and both headlamps, then align and test the cooling system.